

0335

21721-7317

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Company 190th St. & Normandie Ave. Torrance CA 90502		1. Generator's US EPA ID No. C1A1D10181615110101015		A. State Manifest Document Number 86234395		
4. Generator's Phone (213) 533-6677		6. US EPA ID Number		B. State Generator's ID CA-HQ-36-005698 CAD086510005		
5. Transporter 1 Company Name J.C. Liquid Waste Disposal		7. Transporter 2 Company Name		C. State Transporter's ID 709743		
6. US EPA ID Number C1A1D101518101118131617		8. US EPA ID Number		D. Transporter's Phone 213/268-3137		
7. Transporter 2 Company Name		9. Designated Facility Name and Site Address Casmalia P.O. Box E, NTU Road Casmalia, CA93429		E. State Transporter's ID		
10. US EPA ID Number C1A1D10121017141811215		11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		F. Transporter's Phone		
12. Containers		13. Total Quantity		14. Unit Wt/Vol		
No.		Type		I. Waste No.		
a. Waste Corrosive Solid N.O.S. UN1759 Ph 11		0117 DIM 0101014		Y D007-111		
b. Waste Corrosive Solid N.O.S. UN1759		0106 DIM 0101012		Y D002-121		
c. Waste 111 Trichloroethane O.R.M-A UN2831		0152 DIM 0101018		Y D001-352		
d. Waste Flammable Solid N.O.S. UN1325		01013 DIM 0101011		Y D002-271		
J. Additional Descriptions for Materials Listed Above a. Chromic Acid Sludge & Vermiculite. Ph 11 b. Alkaline Solution & Vermiculite. c. Water Contaminated with 111 Trichloroethane & Vermiculite. d. Virgin Resin & Vermiculite.		K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information Guide #32 Casmalia #68 Use gloves, goggles, respirator - Do not go near open flames or inhale fumes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.						
Printed/Typed Name Donald C Garber		Signature Donald C Garber		Month Day Year 1999 8 27		
17. Transporter 1 Acknowledgement of Receipt of Materials		Signature Boone Jeffery		Month Day Year 1999 8 27		
Printed/Typed Name BOONE JEFFERY		Signature		Month Day Year		
18. Transporter 2 Acknowledgement of Receipt of Materials		Signature		Month Day Year		
Printed/Typed Name		Signature		Month Day Year		
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Signature		Month Day Year		
Printed/Typed Name		Signature		Month Day Year		